


Crosscut handsaw fleam guide (fold on center line)

Fleam angle: 5 degrees


Brian Ward <http://www.galootofron.com/>



Crosscut handsaw fleam guide (fold on center line)

Fleam angle: 10 degrees


Brian Ward <http://www.galootofron.com/>



Crosscut handsaw fleam guide (fold on center line)

Fleam angle: 15 degrees

Brian Ward <http://www.galoototron.com/>



Crosscut handsaw fleam guide (fold on center line)

Fleam angle: 20 degrees

Brian Ward <http://www.galootofron.com/>